

L No	RR Number	Account ID	Name	Serial Number	Make	FR	
1	TRPL-1553		MUNIREDDY	22018748	Ladies +GYR	10420	22800
2	TRPL-1556		MUNIREDDY	22018751	Ladies +GYR	08644	13-3-25
3	TRPL-1554	1947825	MUNIREDDY	22018749	Ladies +GYR	16232	13-3-24
4	TRPL-1555	1948179	MUNIREDDY	22018750	Ladies +GYR	13121	
5	TRPL-1557	1948554	MUNIREDDY	22018752	Ladies +GYR	16241	
6	TRPL-1558	1947847	MUNIREDDY	A5393650	Ladies +GYR	39	MS - 0.08
7	TRPL-1559	1955280	MUNIREDDY	A5394298	Ladies +GYR	08291	MS - 0.62
8	TRPL-1560	1947859	MUNIREDDY	220188755	Ladies +GYR	28489	
9	TRPL-AEH-45	1968228	MUNIREDDY	49770513	Ladies +GYR	04660	
10	TRPL-1202			49224644	Ladies +GYR		

Obj:- Column security for elements the above outstaring the Board, while for purpose found that column Demolition existing Building to construct a new Building & this is Adm'n above details for further heedful Action.

Thi P. Pandey
JE & H. D. D. D. D.