


Submitted:-

The installation bearing PRNO. J-6134, J-7336, J-JL-16902
J-JL-16903 to J-JC-16908, I have inspected
the Above installation spot, the existing Building is,
in demolition, the consumer opted to surrender
the installation, the meter is good condition
Kindly surrender along BESCOM Normal

meter Detail as follows:-

SL No	PRNO	MAKE	SL No	RATING	READING
1	J-6134	LEG	BC0285636	5-30A	16419.5 (terminal burned out)
2	J-7336	LEG	BC0986465	5-30A	3591.1
3	J-JL-16902	HPL	38416361	5-30A	3051.0
4	J-JL-16903	HPL	38416362	5-30A	1415.0
5	J-JL-16904	HPL	38416363	5-30A	2158.6
6	J-JL-16905	HPL	38416364	5-30A	1308.8
7	J-JL-16906	HPL	38416365	5-30A	1818.5
8	J-JL-16907	HPL	38416366	5-30A	729.9
9	J-JC-16908	HPL	38416367	5-30A	1788.9

J-6134, Sph. one meter terminal burned out
Kindly collect meter amount


ಕಿರು ಇಂಜಿನಿಯರ್ 27/2/25
ಜಿಲ್ಲಾ ಕಾರ್ಯಾಲಯ
ಜಿಲ್ಲಾ ಕಾರ್ಯಾಲಯ (ಜಿ.ಕೆ.ಸಿ.)